



J. H. FLETCHER & CO. Box 2187 – Huntington, WV 25722-2187 – 304/525-7811 – FAX 304/525-4025

IMPORTANT SAFETY NOTICE

INFORMATION BULLETIN NO. 109

TO: ALL OWNERS AND OPERATORS OF FLETCHER MACHINES THAT HAVE A TEACH/LEARN RADIO TRANSMITTER PART NO. 121274

**FROM: RISK MANAGEMENT DEPARTMENT
J.H. FLETCHER & CO.**

DATE: JULY 10, 2008

SUBJECT: FLETCHER MACHINES THAT HAVE THE TEACH/LEARN RADIO TRANSMITTER ONLY (PART NO. 121274)

J.H. Fletcher & Co. ("Fletcher") has been notified that an error in programming allows two separate radio remote machines to work from the same transmitter. This phenomenon could result in an unintentional movement of a roof bolter. This situation is limited to less than thirty (30) CHDDR machines.

This problem will not occur if you are running only one machine in a section. The possibility of this occurring is when two machines are working in the same section and both machines have been connected to the same transmitter. There have not been any reported injuries or close calls when this situation occurs.

If you believe this scenario is a possibility at your facility, Fletcher recommends you immediately stop using the radio remote unit until Fletcher can fix the problem. **You may continue to use your transmitter (in the umbilical mode) by plugging in the teach/learn cable until the fixes can be made at your mine.** Using both machines with the same transmitter could result in serious injury or death to your operators.

To resolve this problem, Fletcher is taking immediate steps to identify the location of these specific machines in the field and to either reprogram or change out the receiver immediately. The results of this reprogramming of the radios will allow only one receiver to control one roof drill unit.

Information Bulletin 109
July 10, 2008
Page Two

Fletcher will make every effort to change out the roof bolter remote as soon as possible. Until we contact you, we recommend that you;

1. Provide each of your operators with a copy of this bulletin and ensure that they understand and follow it.
2. Post this bulletin in a prominent location for all employees to see.
3. Train all personnel that absolutely no one should stand between the machine and rib during tramming (see warning tag no. 359088 on your machine).

This safety notice affects only machine that have a specifically designed remote control. (See attached list of machines). You will be contacted by Fletcher by next week to arrange for a time to exchange the remote unit. If you have any questions, please do not hesitate to call David P. Cooper, Vice President of Risk Management at (304) 525-7811.

INFORMATION BULLETIN 109
MACHINE LIST FOR PART NO. 121274

MACHINE SERIAL NO.	MACHINE MODEL
2008066	CHDDR-17
2008065	CHDDR-17
2008064	CHDDR-17
2008033	CHDDR-13
2008032	CHDDR-13
2008031	CHDDR-13
2008030	CHDDR-13
2008001	CHDDR-17
2007805(2002042)	CHDDR-13
2007804(2001009)	CHDDR-13
2007039	CHDDR-13
2007026	CHDDR-13
2006457(2001048)	CHDDR-17
2006456(2001047)	CHDDR-17
2006455(2001046)	CHDDR-17
2006093	CHDDR-17
2006092	CHDDR-17
2006091	CHDDR-17
2006090	CHDDR-17
2006061	CHDDR-17
2006060	CHDDR-13
2006056	CHDDR-17
2006031	CHDDR-17
2006030	CHDDR-17
2005062	CHDDR-17
2005048	CHDDR-17
2005042	CHDDR-17