

J. H. FLETCHER & CO. Box 2187 – Huntington, WV 25722-2187 – 304/525-7811 – FAX 304/525-4025

IMPORTANT SAFETY RETROFIT NOTICE

INFORMATION BULLETIN NO. 57

TO: ALL OWNERS, OPERATORS, AND REBUILDERS OF J. H. FLETCHER & CO.
ROOF BOLTING EQUIPMENT

FROM: RISK MANAGEMENT DEPARTMENT
J. H. FLETCHER & CO.

DATE: SEPTEMBER 1995

SUBJ: OFFSET BOOM ARRANGEMENT

Through J. H. Fletcher & Co.'s manufacturing program, new and modernized machines are being equipped with offset booms. This new design provides our customers with advantages such as:

- * the ability to bolt within 15" of the rib
- * increased canopy coverage without increased machine width
- * improved outby access for bolter operators
- * the option of a joystick mounted at the driller's station


If your roof bolter does not have offset booms (see attached), we recommend that you consider updating your machine(s) to this arrangement the next time your machine is modernized.

If you no longer own this equipment, we request that you provide the name and address of the purchaser so we may ensure the current owner receives this information.

If you have any questions, please call our Sales Department at 304/525-7811.

Information Bulletin No. 57
Subject: Offset Boom Arrangement
September 1995

EXAMPLE OF OFFSET BOOMS



NEW DRILL CONTROLS ARRANGEMENT

