



J. H. FLETCHER & CO. Box 2187 – Huntington, WV 25722-2187 – 304/525-7811 – FAX 304/525-4025

IMPORTANT SAFETY RETROFIT NOTICE

INFORMATION BULLETIN NO. 58

TO: ALL OWNERS, OPERATORS, AND REBUILDERS OF J. H. FLETCHER & CO. CDR ROOF BOLTERS, SERIAL NOS. 95021 AND 95022

FROM: RISK MANAGEMENT DEPARTMENT
J. H. FLETCHER & CO.

DATE: JANUARY 1996

SUBJ: CATERPILLAR TRACKS REWORK

J. H. Fletcher & Co. wishes to inform you of a rework program Caterpillar Industrial Products (CIPI) has recently notified us about (see enclosed). A rework is now required on the caterpillar tracks on the two above identified Fletcher roof drills.

The rework will require you to reinstall bolts that are used to mount the final drive to the track roller frame and the sprocket to the final drive.

Upon completion of the work, a CIPI Warranty Claim Form for each set of tracks should be submitted directly to Caterpillar Industrial Products for reimbursement of labor, travel and mileage expenses incurred to complete this rework. J. H. Fletcher & Co. also would appreciate receiving a copy of the completed CIPI Warranty Claim Form(s) for our records; a self-addressed, stamped envelope is enclosed.

To reduce the possibility of a catastrophic component failure, J. H. Fletcher & Co. encourages you to take immediate steps to comply with this rework notice. Your local Fletcher service and sales representatives are available to provide technical assistance.

If you have any questions, please call our Risk Management Department at 304/525-7811, ext. 240.